Qty:

8 Um:

Each

8

: STEP WELDMENT

: D2563

: N/A

:NA

: 6/30/2006

: C

: D2563 REV C

Date:

Monday, 6/5/2006 11:00:56 AM

User:

Kim Johnston

Process Sheet

Drawing Name

Part Number

Material **Due Date**

Drawing Number

Project Number

Drawing Revision

Customer Job Number : CU-DAR001 Dart Helicopters Services

Estimate Number

: 27404 : 10176

Al4:

P.O. Number

This Issue

: 6/5/2006

: NC Prsht Rev.

First Issue **Previous Run**

: 25944A

: NIA

S.O. No. : NIA

Type

: LARGE FAB ASSY

Checked & Approved By

Comment

Written By

Additional Product

Job Number:



Sea. #:

Machine Or Operation:

Description: Step Extrusion

1.0 D2244116

Comment: Qty.:

1.0000 Each(s)/Unit Total:

8.0000 Each(s)

Pick:

D2244 Step Extrusion

Batch: 323404

2.0

End Plate

Total:



Comment: Qtv.:

2.0000 Each(s)/Unit Pick:

Qtv Part No.

2

Description

Batch **3** 25396

Lug Plate

D2673-34 End Cap

16.0000 Each(s)

P. 06.06.26

3.0

D2561

Comment: Qty.:

2.0000 Each(s)/Unit Total:

16.0000 Each(s)

Pick:

Qty Part No.

Description

D2561 Lug Plate

327417 =5

4.0

2 D2564

Comment: Qty.:

2.0000 Each(s)/Unit Total:

16.0000 Each(s)

Pick:

2

Qty Part No.

Description

D2564 Mounting Angle Batch **3 25910**

SE 06.06.268

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
·	1:1						
		ere i		•			

NCR:			WORK ORDI	ER NON-CONFORMANCI	(NCR)							
		Description of NC		Corrective Action Section B		Verification	A	Approval QC Inspector				
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Approval Design Mgr					
	12		4									
•		•										
				- 15.								
		4		•								
				:		*	-					
					÷	,						

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA: _	Date:	
NOTE: Date & initial all entries				QA:	N/C C	losed: _	 Date:	, 1

Date: Monday, 6/5/2006 11:00:56 AM User: Kim Johnston **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: STEP WELDMENT** Job Number: 27404 Part Number: D2563 Job Number: Seq. #: **Machine Or Operation:** Description: LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 16.06.06.26 1-Cut D2244 to 89.70" at 34° as per Dwg D2563 1.6.06.06.26 2-Deburr ends I.E. 06.06.27 3-Weld (1 End Only) as per Dwg D2563 using DT 8343 Batch: *M19763* A/R AL ROD FF 06.06.27 4-Grind 6.0 QC5/9 WELD INSPECTION Comment: WELD INSPECTION HAND FINISHING RESOURCE #1 7.0 HAND FINISHING Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 INSPECT POWDER COAT/CHEMICAL CONVERSIO 66.06.20 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 9.0 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1-Inspect for foreign object per QSI 024 2-Weld Remainig End as per Dwg D2563 using DT 8343 A/R AL ROD Batch: m 100660 3-Grind 10.0 QC5/9 WELD INSPECTION **Comment: WELD INSPECTION**

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES	WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector					

NCR:	9		WORK ORI	DER NON-CONFORMANCE	(NCR)			
		STED Description of NC		Corrective Action Section B		Verification	Approval-	Annaval
·DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	n Sign & Section C	Design Mgr	Approval QC Inspector	
			-					
					·			
					8.			
					•			
				;				
) ·	***	

Part No:	PAR #:	Fault Category: _	 NCR:	Yes No DQA:	 	Date: 06	107/06
NOTE: Date & initial all entries				QA: N/C Closed:		Date:	

Date: Monday, 6/5/2006 11:00:56 AM User: Kim Johnston **Process Sheet Drawing Name: STEP WELDMENT** Customer: CU-DAR001 Dart Helicopters Services Job Number: 27404 Part Number: D2563 Job Number: Seq. #: Description: **Machine Or Operation:** POWDER COATING POWDER COATING 11.0 Comment: POWDER COATING 05.06.29 Touch up Alodine then Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 HAND FINISHING1 HAND FINISHING RESOURCE #1 12.0 Comment: HAND FINISHING RESOURCE #1 Wing Walk as per Dwg D2563 and QSI 005 4.4 13.0 INSPECT POWDER COAT/CHEMICAL CONVERSIO QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION DOCUMENT CONTROL 14.0 DC Comment: DOCUMENT CONTROL Inspection Level 21 U 06-07.55 Job Completion

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES									
DATE	STEP		PROCEDURE CHANGE			Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector		
						3.30					
·		4									
		Section 1									
				i.							
		· · · · · · · · · · · · · · · · · · ·									

NCR:			WORK ORDI	ER NON-CONFORMAN	CE (NCR)								
		Description of NC		Corrective Action Section B		Vifiti	Approval Design Mgr						
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Verification Section C		Approval QC inspector					
		* *											
		90		·									
		*											
		-											
	- 3												
					10.50								
								:					

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	Date:	
NOTE: Date & initial all entries				QA: N	N/C C	losed:	Date:	

